
- Speedometer Calibration Certificate -



The speedometer head and gear train drive have been checked in the above described vehicle and compared for accuracy. The results of the test and the actual speeds of the vehicle are listed below.

Speedometer Reading	Calibration Chart	Actual Speed	Speedometer Calibrat Reading Char	
25		25	55	88
30		30	60	60
35		35	65	68
40		40	70	70
45		45	75	78
50		50	80	80
	C	ertified by	fith	2
	T	he above tests w	vere performed on 5	18hy

(1)

11.00

1(.)

## Certified Speedometer Serbice Inc. 9 Jay Street, Old Tappan, N.J. 07675

9 Jay Street, Glo Cappan, N.J. 0767 (201) 664-7759

- Speedometer Calibration Certificate -

Fort	2017		TOWN	10	4949	187474
MAKE	YEAR OF MFF	1.	CAR NO.		MILEAGE	LICENSE NUME
	r head and gear the					
	curacy. The resul		est and the			
Speedometer Reading	Calibration Chart	Actual Speed		Speedometer Reading	Calibration Chart	Actual Speed
25		25		55		55
30		30		60		60
35		35		65		65
40		40		70		70
e 45		45	777 (M) (M) (M)	75		75
50		50		80	Da	KO
	Се	rtified by		Jon 7	sty	

© GOES 34625

Cer

 $(\cdot)$ 


(...)

 $(\cdot)$ 

 $( \cdot )$ 

11.5

**Certified Speedometer Serbice Inc.** 9 Jay Street, Old Tappan, N.J. 07675 (201) 664-7759 - Speedometer Calibration Certificate -



The above tests were performed on

 $((\cdot))$ 

LITHO IN U.S.A.

Certified by

© GOES 34625

 $((\cdot))$ 

 $((\cdot))$ 


 $((\cdot))$ 

 $((\cdot))$ 

de.s

(1)

- Speedometer Calibration Certificate -



 $(\cdot)$ 

 $(\cdot)$ 

LITHO IN U.S.A


© GOES 34625

 $((\cdot))$ 


 $(( \cdot ))$ 




- Speedometer Calibration Certificate -



The speedometer head and gear train drive have been checked in the above described vehicle and compared for accuracy. The results of the test and the actual speeds of the vehicle are listed below.



- Speedometer Calibration Certificate -



© GOES 34625

 $((\cdot))$ 

 $((\cdot))$ 

((·))

((··))

LITHO IN U.S.A.

 $((\cdot))$ 

 $((\cdot))$ 


 $((\cdot))$ 

 $(\cdot)$ 

- Speedometer Calibration Certificate -









LITHO IN U.S.A.

The speedometer head and gear train drive have been checked in the above described vehicle and compared for accuracy. The results of the test and the actual speeds of the vehicle are listed below.

Speedometer Reading	Calibration Chart	Actual Speed	Speedometer Reading	Calibration Chart	Actual Speed
25		25	55		55
30		30	60	-	60
35		35	65		65
40		40	70		70
45		YE	75		25
50		50	80	0	80
	(	Certified by		Ala	Int
	J	The above tests v	vere performed øn	1 11-	-8-19

Cer Ex

6-1

 $((\cdot))$ 

 $(1 \cdot )$ 

